

<:nav id=mobile-nav class=mobile-nav sizcache="60" sizset="1">

EPA Menu



Detailed Facility Report

Facility Summary

GEORGIA PACIFIC, LLC-N LOG YRD
HWY 80, BEHIND GP PLYWOOD FAC., CROSSETT, AR 71635

Facility Information (FRS)

FRS ID: 110010064429

EPA Region: 06

Latitude: 33.149444

Longitude: -91.958889

Industry:

Indian Country: --

Regulatory Interests

Clean Air Act:

Clean Water Act: Minor, Permit Effective (AR0048097)

Resource Conservation and Recovery Act:

Safe Drinking Water Act:

Also Reports

Air Emissions Inventory (EIS):

Greenhouse Gas Emissions (eGGRT):

Toxic Releases (TRI):

Enforcement and Compliance Summary

Statute	Insp (5 Years)	Date of Last Inspection	Current Compliance Status	Qtrs in NC (of 12)	Qtrs in Significant Violation	Informal Enforcement Actions (5 years)	Formal Enforcement Actions (5 years)	EPA Cases	Penalties (5 years)
CWA	1	05/30/2012	No Violation	5	0	--	--	--	--

Facility/System Characteristics

Facility/System Characteristics

Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
CWA	AR0048097	Minor: NPDES Individual Permit	Effective	--	11/30/2016	--	33.149444	-91.958889

Facility Contact Information

System	Identifier	Facility Name	Facility Address	Contact Name	Contact Telephone
FRS	110010064429	GEORGIA PACIFIC, LLC-N LOG YRD	HWY 80, BEHIND GP PLYWOOD FAC., CROSSETT, AR 71635	x	x
ICP	AR0048097	GEORGIA PACIFIC, LLC - NORTH LOG YARD	OLD ROBINSON ROAD, CROSSETT, AR 71635	x	x

Facility SIC Codes

System	Identifier	SIC Code	SIC Desc
ICP	AR0048097	2411	--

Facility NAICS Codes

System	Identifier	NAICS Code	NAICS Desc
ICP	AR0048097	113310	Logging

Enforcement and Compliance

Compliance Monitoring History (5 years)

Statute	Source ID	System	Inspection Type	Lead Agency	Date	Finding
CWA	AR0048097	ICP	Evaluation	State	05/30/2012	--

Compliance Summary Data

Statute	Source ID	Current SNC/HPV	Description	Current As Of	Qtrs in NC (of 12)
CWA	AR0048097	--	--	01/04/2014	5

Three Year Compliance Status by Quarter

Statute	Program/Pollutant/Violation Type	QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11	QTR 12
CWA	(Source ID: AR0048097)	10/01-12/31 2010	01/01-03/31 2011	04/01-06/30 2011	07/01-09/30 2011	10/01-12/31 2011	01/01-03/31 2012	04/01-06/30 2012	07/01-09/30 2012	10/01-12/31 2012	01/01-03/31 2013	04/01-06/30 2013	07/01-09/30 2013
	Facility-Level Status	In Viol	In Viol	In Viol	No Viol	In Viol	No Viol	No Viol	No Viol	In Viol	No Viol	No Viol	No Viol
	SNC/RNC History	N (RptViol)	N (RptViol)	N (RptViol)	R(Resolved)	V (NonRNCV)	--	--	--	V (NonRNCV)	--	--	--
	Permit Schedule Violations												
CWA	Schedule Event achieved late but reported: Status/Progress Report	--	--	--	--	--	--	--	--	12-01-12-12-12	--	--	--

Informal Enforcement Actions (5 Years)

Statute	Source ID	Type of Action	Lead Agency	Date
No data records returned				

Formal Enforcement Actions (5 Years)

Statute	Source ID	Type of Action	Lead Agency	Date	Penalty	Penalty Description
No data records returned						

ICIS Case History

Primary Law/Section	Case No.	Case Type	Lead Agency	Case Name	Issued/Filed Date	Settlement Date	Federal Penalty	State/Local Penalty	SEP Cost	Comp Action Cost
No data records returned										

Environmental Conditions

Water Quality

Permit ID	Watershed (HUC 8)	Watershed Name (HUC 8)	Watershed (HUC 12)	Watershed Name (HUC 12)	Receiving Waters	Impaired Waters	Combined Sewer System?
AR0048097	08040202	LOWER OUACHITA-BAYOU DE LOUITRE	080402020204	Headwaters Brushy Creek	TRIB.LTL BRUSHY CR,BIG BRUSHY CR,BRUSHY CR,MARAIS	No	--

Air Quality

Non-Attainment Area?	Pollutant(s)
No	Ozone
No	Lead
No	Particulate Matter

Pollutants

TRI History of Reported Chemicals Released in Pounds per Year at Site

Year	Total Air Emissions	Surface Water Discharges	Underground Injections	Releases to Land	Total On-site Releases	Total Off-site Releases
No data records returned						

TRI Total Releases and Transfers by Chemical and Year

Chemical Name
No data records returned

Demographic Profile

Demographic Profile of Surrounding Area (3 Miles)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2010 US Census and American Community Survey data, and are accurate to the extent that the facility latitude and longitude listed below are correct. The latitude and longitude are obtained from the EPA Locational Reference Table (LRT) when available.

Radius of Area:	3	Land Area:	99%	Households in Area:	3,880
Center latitude:	33.149444	Water Area:	1%	Housing Units in Area:	4,460
Center Longitude:	-91.958889	Population Density:	335/sq.mi.	Households on Public Assistance:	154
Total Persons:	9,399	Percent Minority:	36%	Persons Below Poverty Level:	4,297
Race Breakdown		Persons (%)		Age Breakdown	
White:		6,033 (64.19%)		Child 5 years and younger:	
African-American:		3,099 (32.97%)		Minors 17 years and younger:	
Hispanic-Origin:		218 (2.32%)		Adults 18 years and older:	
Asian/Pacific Islander:		31 (.33%)		Seniors 65 years and older:	
American Indian:		20 (.21%)			
Other/Multiracial:		216 (2.3%)			
Education Level (Persons 25 & older)		Persons (%)		Income Breakdown	
Less than 9th Grade:		211 (3.39%)		Less than \$15,000:	
				769 (12.35%)	


Education Level (Persons 25 & older)	Persons (%)	Income Breakdown	Households (%)
9th through 12th Grade:	757 (12.16%)	\$15,000 - \$25,000:	626 (16.1%)
High School Diploma:	2,953 (47.42%)	\$25,000 - \$50,000:	1,004 (25.82%)
Some College/2-yr:	1,537 (24.68%)	\$50,000 - \$75,000:	718 (18.46%)
B.S./B.A. or More:	769 (12.35%)	Greater than \$75,000:	662 (17.02%)

GEORGIA PACIFIC AERIALS

Aerial #1 – City of Crossett, Georgia-Pacific Complex, & Wastewater Treatment System



Aerial #2 – Southern Segment of Wastewater Treatment System & Outfall to Ouachita River




GEORGIA PACIFIC AERIALS

Aerial #3 – Close-in View of Wastewater Treatment System



Aerial #4 – Aeration Stabilization Basin



GEORGIA PACIFIC AERIALS

Aerial #5 – Surge Basin (two cement channels run entire length)



Aerial #6 – City of Crossett Municipal Wastewater Lagoon



GEORGIA PACIFIC AERIALS

Aerial #7 – West & East [Ash] Settling Basins




Aerial #8 – Reclamation Area



GEORGIA PACIFIC AERIALS

Aerial #9 – Primary Clarifier



Aerial #10 – North & South Stormwater Conveyances; P1 & P3; Primary Clarifier



GEORGIA PACIFIC AERIALS

Aerial #11 – Higher Altitude View of Aerial #10



Aerial #12 – Further Upstream from Aerial #11



GEORGIA PACIFIC AERIALS

Aerial #13 – Upstream of Aerial #12 & Entrance to Plant




Aerial #14 – Confluence of P2 & P1; P1 & P3 on Plant Site



GEORGIA PACIFIC AERIALS

Aerial #15 – P1 & P3 Open Sewers on Plant Site



Aerial #16 – Close-in View of Aerial #15

